



I think I need a fixed oxygen (O2) monitor

What is the threat gases you are concerned will deplete your O2?

Nitrogen or Argon and Helium

Nitrogen and/or Argon

Carbon Dioxide (& any of N2, Ar or He)

Other

You need an O2NE He

You need an O2NE

You need an Ax50 CO2 monitor

Please call us to discuss as we have various options



We offer 2 versions of the O2NE

1. The standard O2NE (sensor lasts approx 2 years and calibration required every 6 months)
2. The 10 Year O2NE (sensor lasts 10 years and calibration required every 18 months)



We can also offer the following optional extras for your O2 depletion monitor. Please contact us to discuss your needs further.

If you also store liquid O2 you may be interested in our Safe-Ox monitor (also available in 10 year version)

If you are concerned about your power supply we can offer battery back up?

If you'd like your O2NE to trigger a fan or remote alarm we can offer relays or 4-20mA

The O2NE comes with 1 x repeater for 1 x doorway. If you have extra doorways we can offer additional repeaters

If your monitor is in a particularly low lit area we can offer high intensity strobe lights onto your repeater for extra visibility

You may also be interested in our portable O2 and CO2 personal monitors

